E.E. Zimmerman Company/Elroy Turpentine Company P.O. Box 111254 Pittsburgh, PA 15238 (412) 963-0949

MATERIAL SAFETY DATA SHEET

E-Z HIGH SOLVENCY ACETONE

EMERGENCY CONTACT: FOR CHEMICAL EMERGENCY - SPILL, LEAK, FIRE, EXPOSURE, OR ACCIDENT,

CALL CHEMTREC AT 1-(800)-424-9300, DAY OR NIGHT.

Prepared: 5/05

NFPA INDEX **HMIS** 4 - Extreme Health 1 Health 1 Flammability Flammability 3 - High 3 3 2 - Moderate Physical Hazard 0 Reactivity 0

1 - Slight 0 - Least

Section 2. COMPOSITION/INFORMATION ON INGREDIENTS

COMPONENT C.A.S. No. AMOUNT (VOL.%)

67 - 64 - 1 **ACETONE** 100

EXPOSURE GUIDELINES (SEE SECTION 15 FOR ADDITIONAL EXPOSURE LIMITS)

	<u>C.A.S. No.</u>	<u>Governing Body</u>	Exposure Limits	
Limit for the product	67-64-1	ACGIH	STEL	750 ppm
Limit for the product	67-64-1	ACGIH	TWA	500 ppm
Limit for the product	67-64-1	OSHA	TWA	1000 ppm

Section 3. HAZARDS IDENTIFICATION

EMERGENCY OVERVIEW:

Danger! Extremely flammable liquid and vapor. Vapors may cause flash fire or explosion. Harmful if inhaled. High vapor concentrations may cause drowsiness. Causes skin and eye irritation. Harmful if swallowed. May cause target organ or system damage to the following: Eye, Skin, Respiratory system, Central nervous system.

POTENTIAL HEALTH EFFECTS:

PRE-EXISTING MEDICAL CONDITIONS:

The following diseases or disorders may be aggravated by exposure to this product: Skin, Eye, Lung (asthma-like conditions).

INHALATION

High concentrations may lead to central nervous system effects (drowsiness, dizziness, nausea, headaches, paralysis and loss of consciousness and even death). High vapor concentrations are irritating to the eyes, nose, throat and lungs.

LC50 (mg/l): no data

LC50 (mg/m3): rat; 8hrs. 50000

LC50 (ppm): no data

SKIN

Moderately irritating to the skin. Prolonged or repeated contact can result in defatting and drying of the skin which may result in skin irritation and dermatitis (rash).

Draize Skin Score: Out of 8.0 no data LD50 (mg/kg): rabbit 20000 **EYES**

Contact with the eye may cause moderate to severe irritation.

INGESTION

Product may be harmful or fatal if swallowed. Pulmonary aspiration hazard. After ingestion, may enter lungs and produce damage. May produce central nervous system effects, which may include dizziness, loss of balance and coordination, unconsciousness, coma and even death.

LD50 (g/kg):

rat

5.8

Section 4. FIRST AID MEASURES

INHALATION

Remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen and continue to monitor. Get immediate medical attention.

SKIN

Immediately flush skin with plenty of water. Remove clothing. Get medical attention immediately. Wash clothing separately before reuse.

EYES

Flush eye with water for 15 minutes. Get medical attention.

INGESTION

If swallowed, do NOT induce vomiting. Give victim a glass of water or milk. Call a physician or poison control center immediately. Never give anything by mouth to an unconscious person. Get medica attention immediately. See Section 15 for additional first aid information.

Section 5. FIRE FIGHTING MEASURES

EXTINGUISHING MEDIA

Water spray, Alcohol resistant foam, Dry chemical, Carbon dioxide

FIRE FIGHTING INSTRUCTIONS

Use water spray. Use water spray to cool fire exposed tanks and containers. Acetone/water solutions that contain more than 2.5% acetone have flash points. When the acetone concentration is greater than 8% (by weight) in a closed container, it would be within the flammable range and cause fire or explosion if a source of ignition were introduced.

FLAMMABLE PROPERTIES

<u>l ypical</u>	<u>Minimum</u>	<u>Maximum</u>	Text Result	<u>Units</u>	<u>Method</u>
1.4				F	N/A
869				F	N/A
2.5				%	N/A
12.8				%	N/A
	1.4 869 2.5	1.4 869 2.5	1.4 869 2.5	1.4 869 2.5	1.4 F 869 F 2.5 %

Section 6. ACCIDENTAL RELEASE MEASURES

Prevent ignition, stop leak and ventilate the area. Contain spilled liquid with sand or earth. DO NOT use combustible materials such as sawdust. Use appropriate personal protective equipment as stated in Section 8 of this MSDS. Advise the Environmental Protection Agency (EPA) and appropriate state agencies, if required. US regulations require reporting spills of this material that could reach any surface waters. The toll free number for the US Coast Guarc National Response Center is (800) 424 - 8802. After removal, flush contaminated area thoroughly with water.

Section 7. HANDLING AND STORAGE

HANDLING

Use only in well-ventilated area. Ground and bond containers when transferring material. Avoid breathing (dust, vapor, mist, gas). Avoid contact with this material. Wash thoroughly after handling. Do not use air pressure to unload containers.

STORAGE

Keep away from heat, sparks and flame. Store in a cool dry place. Keep container closed when not in use.

Page 2 of 6

Section 8. EXPOSURE CONTROLS/PERSONAL PROTECTION

Consult with a Health and Safety Professional for Specific Selections

ENGINEERING CONTROLS

Use with adequate ventilation. Ventilation is normally required when handling or using this product to keep exposure to airborne contaminants below the exposure limit. Use explosion-proof ventilation equipment.

PERSONAL PROTECTION

EYE PROTECTION

Splash proof chemical goggles or full face shield recommended to protect against splash of product.

GLOVES or HAND PROTECTION

The glove(s) listed below may provide protection against permeation. Gloves of other chemically resistant materials may not provide adequate protection. Protective gloves are recommended to protect against contact with product. Neoprene; Natural rubber

RESPIRATORY PROTECTION

Concentration in air determines the level of respiratory protection needed. Use only NIOSH certified respiratory equipment. Half-mask air purifying respirator with organic vapor cartridges is acceptable for exposures to ten (10) times the exposure limit. Full-face air purifying respirator with organic vapor cartridges is acceptable for exposures to fifty (50) times the exposure limit. Exposure should not exceed the cartridge limit of 1000ppm. Protection by air purifying respirators is limited. Use a positive pressure-demand full-face supplied air respirator or SCBA for exposures greater than fifty (50) times the exposure limit. If exposure is above the IDLH (Immediately Dangerous to Life and Health) or there is the possibility of an uncontrolled release, or exposure levels are unknown, then use a positive pressure-demand full-face supplied air respirator with escape bottle or SCBA. Wear a NIOSH-approved (or equivalent) full-facepiece airline respirator in the positive pressure mode with emergency escape provisions.

OTHER

The following materials are acceptable for use as protective clothing: Neoprene; Natural rubber. Facilities storing or utilizing this material should be equipped with an eyewash facility and a safety shower. Remove contaminated clothing and wash before reuse.

Section 9. PHYSICAL AND CHEMICAL PROPERTIES

PHYSICAL PROPERTY Appearance	TYPICAL	<u>UNITS</u> N/A	TEXT RESULT Colorless liq	REFERENCE
Boiling Point	133	F		
Bulk Density		lb/gal	No data	
Melting Point	-137.2	F		
Molecular Weight	58.08	g/mole		
Octanol/Water Coefficient		N/A	No data	
рН	7	N/A		
Specific Gravity	0.79	N/A		
Solubility in Water		wt %	Complete	
Odor		N/A	Sweet pungent	
Odor Threshold	62	ppm		
Vapor Pressure	181	mmHg	@20 C	
Viscosity (F)		SUS	No data	
Viscosity (C)		CsT	No data	
% Volatile	100	wt %		

Section 10. STABILITY AND REACTIVITY

CONDITIONS TO AVOID

Avoid heat, sparks and open flame.

INCOMPATIBILITY

Acetone may form explosive mixtures with chromic anhydride, chromyl alcohol, hexachloromelamine, hydrogen peroxide, permonosulfuric acid, potassium tertbutoxide and thioglycol. Strong oxidizers.

HAZARDOUS DECOMPOSITION PRODUCTS

Combustion may produce carbon monoxide, carbon dioxide and other asphyxiants.

HAZARDOUS POLYMERIZATION

Will not polymerize.

Section 11. ECOLOGICAL INFORMATION

This product is not expected to persist in the environment.

Section 12. DISPOSAL CONSIDERATIONS

Follow federal, state and local regulations. In Canada, follow federal, provincial and local regulations. This material is a RCRA hazardous waste. Do not flush material to drain or storm sewer. Contract to authorized disposal service.

Section 13. TRANSPORT INFORMATION

GOVERNING BODY	<u>MODE</u>	PROPER SHIPPING NAME	<u>CONTAINER MODE</u>
----------------	-------------	----------------------	-----------------------

DOT Ground ACETONE, 3, UN1090, II 55 Gal Drum/5 Gal Pail/Gallon

GOVERNING BODY MODE PROPER SHIPPING NAME CONTAINER MODE

DOT Ground CONSUMER COMMODITY, ORM-E Quart/Pint

OTHER TRANSPORT INFORMATION

The DOT Transport Information may vary with the container and mode of shipment.

Section 14. REGULATORY INFORMATION

<u>REGULATORY LIST</u>	<u>COMPONENT</u>	CAS NO.
ACGIH 2000 - Short Term Exposure Limits	Acetone	67-64-1
ACGIH 2000 - Time Weighted Averages	Acetone	67-64-1
Canada - WHMIS: Ingredient Disclosure	Acetone	67-64-1
CERCLA/SARA - Haz Substances and their RQs	Acetone	67-64-1
Inventory - Canada - Domestic Substances List	Acetone	67-64-1
Inventory - European EINECS Inventory	Acetone	67-64-1
Inventory - Japan - (ENCS)	Acetone	67-64-1
Inventory - Korea - Existing and Evaluated	Acetone	67-64-1
Inventory - TSCA - Sect. 8(b) Inventory	Acetone	67-64-1
Massachusetts Right To Know List	Acetone	67-64-1
New Jersey - Department of Health RTK List	Acetone	67-64-1
New Jersey - Special Hazardous Substances	Acetone	67-64-1
OSHA - Final PELs - Time Weighted Averages	Acetone	67-64-1
Pennsylvania Right to Know List	Acetone	67-64-1
TSCA - Sect. 12 (b) - Export Notification	Acetone	67-64-1

TITLE III CLASSIFICATIONS SECTIONS 311, 312

Acute YES
Chronic NO
Fire YES
Reactivity NO
Sudden Release of Pressure

Section 15. OTHER INFORMATION

If swallowed, acetone should be removed by emesis and/or gastric lavage. Mechanical assisted ventilation may be necessary. In severe cases, an initial period of hypoglycemia may require correction by intravenous solutions of dextrose. In some cases, an initial period of hyperglycemia has occurred during the recovery phase and has lasted for a few days. Treatment with insulin may be beneficial but should be used cautiously. Empty containers retain product residue (liquid and/or vapor) and can be dangerous. Do not pressurize, cut, weld, braze, solder, drill, grind or expose such containers to heat, flame, sparks, static electricity or other sources of ignition. They may explode and cause injury or death. Empty drums should be completely drained, properly bunged and promptly returned to a drum reconditioner or properly disposed of. This product is subject to the Chemical Diversion and Trafficking Act of 1988 and subject to specific record keeping requirements. WHMIS Classification: Class B Division 2 - Flammable liquids;

E.E. Zimmerman Company/Elroy Turpentine Company believes that the statements, technical information and recommendations contained herein are reliable, but they are given without warranty or guarantee of any kind, express or implied, and we assume no responsibility for any loss, damage, or expense, direct or consequential, arising out of their use.