Safety Data Sheet

Product Name: Liquid Luster

SDS Date: 1/12/2016

1. PRODUCT AND COMPANY IDENTIFICATION

Product Name: Liquid Luster

Manufacturer: CB Glass

1560 Craft Center Drive Smithville TN 38582 615-597-6801 Ext 124

Emergency Phone number: Chemtrec

Toll Free: 800-424-9300 International: +703-527-3887

2. HAZARDS IDENTIFICATION

Classification of the mixture: Flammable Liquids - Category 4

Skin sensitization - Category 1



Hazard Statements

Danger H227 Combustible liquid H302 Harmful if swallowed

H318 Causes serious eye damage H317 May cause an allergic skin reaction

Precaution Statements

Wear protective gloves
Wear eye or face protection
Wear protective clothing
Keep away from flames and hot surfaces
Avoid breathing vapor
Do not eat, drink, or smoke when using this product
Wash hands throughly after handling
Contaminated work clothing should not be allowed out of the workplace

Response:

If Inhaled: Remove victim to fresh air and keep at rest in a position comfortable for breathing. Immediately call a Poison Center or physician.

If Swallowed: Immediately call a Poison Center or physician. Rinse mouth. Do NOT induce vomiting.

If on skin: Take off immediately all contaminated clothing. Rinse skin with water. Wash contaminated clothing before reuse.

If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.

Call a Poison Center or physician if you feel unwell. If eye irritation persists, get medical attention.

Storage:

Store locked up P403 Store in a well ventilated place. P235 Keep cool

Disposal:

P501 Dispose of contents and container in accordance with all local, regional, national and international regulations.

Other hazards which do not result in classification:

None known.

2. COMPOSITION AND INFORMATION ON INGREDIENTS

Component	CAS#	Concentration
Solvent naphtha (petroleum)	64742-88-7	41–50%

Tung oil	8001-20-5	<5%
Toluene	108-88-3	<1%
Triethylamine	121-44-8	<1%
Ethylbezone	100-41-4	<1%
Manganese Carboxylate	7439-96-5	<1%
Cobalt compounds	7440-48-4	<1%

4. FIRST AID MEASURES

Inhalation: Remove to fresh air. If not breathing, give artificial

respiration. If breathing is difficult, give oxygen. Use oxygen as required, provided a qualified operator is

present. Call a physician.

Skin Contact: Wash off immediately with plenty of water for at least 15

minutes. Take off contaminated clothing and shoes immediately. Wash contaminated clothing before reuse.

Call a physician if irritation develops or persists.

Eye Contact: Rinse immediately with plenty of water, also under the

eyelids for at least 15 minutes. Call a physician,

preferably an ophthalmologist.

Ingestion: Do not induce vomiting without medical advice.

Immediate medical attention is required. Never give anything by mouth to an unconscious person. Call a

physician.

Notes to Physician

Treatment: Treat symptomatically.

5. FIRE-FIGHTING MEASURES

Flash Point: 45° C (113° F)

Ignition temperature: 399° C (750° F)

Lower explosion limit: 0.0% @ 77°F

Upper explosion limit: 6% @ 77°F

Suitable extinguishing media: Alcohol resistant foam

Suitable extinguishing media: Carbon dioxide (CO₂)

Dry Chemical

Cool closed containers exposed to fire with water

spray.

Extinguishing media which shall not

be used for safety reasons:

Do not use a solid water stream as it may scatter and

spread fire.

Specific hazards during fire fighting: Flammable.

Vapors may form explosive mixtures with air.

Specific hazards during fire fighting: Vapors are heavier than air and may spread along

floors.

Vapors may travel to areas away from work site before

igniting back to vapor source.

In case of fire, hazardous decomposition products may

be produced such as:

carbon monoxide

carbon dioxide (CO₂)

Special protective equipment for

fire-fighters:

Wear self-contained breathing apparatus and protective

suit.

6. ACCIDENTAL RELEASE MEASURES

Personal precautions: Wear personal protective equipment

Immediately evacuate personnel to safe areas.

Keep people away from and upwind of spill.

Ensure adequate ventilation.

Remove all sources of ignition.

Do not swallow.

Avoid breathing vapors, mist or gas.

Avoid contact with skin, eyes and clothing.

Environmental precautions: Prevent further leakage or spillage if safe to do so.

Discharge into the environment must be avoided.

Environmental precautions: Do not flush into surface water or sanitary sewer

system.

Prevent product from entering drains.

Collect contaminated fire extinguishing water separately. This must not discharge into drains.

Methods for clean-up: Ventilate the area.

No sparking tools should be used.

Use explosion proof equipment.

Methods for clean-up: Contain and collect spillage with non-combustible

absorbent materials, e.g. sand, earth, vermiculite,

diatomaceious earth and place in container for disposal

according to local regulations (see section 13).

7. HANDLING AND STORAGE

Handling

Handling: Wear personal protective equipment.

Use only in well ventilated areas.

Keep container tightly closed.

Do not smoke.

Do not swallow.

Avoid breathing vapors, mist or gas.

Avoid contact with skin, eyes and clothing.

Advice on protection against

fire and explosion:

Keep away from fire, sparks and heated surfaces.

Take precautionary measures against static discharges.

Ensure all equipment is electrically grounded before

beginning transfer operations.

Use explosion proof equipment.

Keep product and empty container away from heat and

sources of ignition.

No sparking tools should be used.

No smoking.

Storage

Requirements for storage areas and containers:

Store in area designed for storage of flammable liquids.

Protect from physical damage.

Keep containers tightly closed in dry, cool and well ventilated

place.

Containers which are opened must be carefully resealed and

kept upright to prevent leakage.

Keep away from heat and sources of ignition.

Requirements for storage areas and containers:

Keep away from direct sunlight.

Store away from incompatible substances.

Container hazardous when empty.

Do not pressurize, cut, weld, braze, solder, drill, grind or

expose containers to heat or sources of ignition.

8. EXPOSURE CONTROL / PERSONAL PROTECTION

Protective Measures: Ensure that eyewash stations and safety showers are close

to the workstation location.

Engineering measures: Use with local exhaust ventilation.

Prevent vapor buildup by providing adequate ventilation

during and after use.

Eye protection: Do not wear contact lenses.

Wear safety glasses with side shields.

Hand protection: Solvent resistant gloves.

Skin and body protection: Solvent resistant apron.

Flame retardant antistatic protective clothing.

Respiratory protection: In case of sufficient ventilation wear suitable respiratory

equipment.

Hygiene measures: When using, do not eat or drink or smoke.

Hygiene measures: Wash hands before breaks and immediately after handling

the product.

Keep work clothes separate.

Remove and wash contaminated clothing before re-use.

Do not swallow.

Avoid breathing vapors, mist or gas.

Avoid contact with skin, eyes and clothing.

Exposure Guidelines

Component	Туре	Value
Toluene	TWA	200ppm
Triethylamine	TWA	25ppm
Ethylbenzene	TWA	100ppm

9. PHYSICAL AND CHEMICAL PROPERTIES

Form: colored liquid

Color: amber

Odor: Oily hydrocarbon

Solids volume 26.5297%

Solids weight 33%

Material VOC 407,181 lbs/gal

Material VOC 566.6014 g/l

Weight per gallon 7.0681

10. STABILITY AND REACTIVITY

Stable

Conditions to avoid Heat, sparks, flame and oxidizing agents

Caustic amines

alkanoamines

and inorganic acids

Contact with water

Chemical incompatibility Strong oxidizing agents.

Strong acid

Water

11. TOXICOLOGICAL INFORMATION

Skin irritation: rabbit

Mild skin irritation

Eye irritation: rabbit

Severe eye irritation

12. ECOLOGICAL INFORMATION

Ecological Toxicity Values no data available

13. DISPOSAL CONSIDERATIONS

Observe all Federal, State and Local Environmental regulations.

14. TRANSPORT INFORMATION

DOT Classification:

Proper shipping name: Paint

Class:	3	
UN ID#:	UN1263	
Packing Group:	II	
IATA Classification:		
Proper shipping name:	Paint	
Class:	3	
UN ID#:	UN1263	
Packing Group:	II	
15. REGULATORY INFO	ORMATION	
13. HEAGLAIGHT INFO	JI IIII ATTON	
TSCA TSCA		
	SARA 313 reportable 0.79%	
TSCA Toluene	SARA 313 reportable 0.79%	
TSCA		
TSCA Toluene	SARA 313 reportable 0.79%	
TSCA Toluene	SARA 313 reportable 0.79% SARA 313 reportable 0.2%	
TSCA Toluene Triethylamine	SARA 313 reportable 0.79% SARA 313 reportable 0.2%	NFPA
TSCA Toluene Triethylamine 16. OTHER INFORMATION	SARA 313 reportable 0.79% SARA 313 reportable 0.2%	NFPA 2
TSCA Toluene Triethylamine 16. OTHER INFORMATION Health:	SARA 313 reportable 0.79% SARA 313 reportable 0.2% ON HMIS III	
TSCA Toluene Triethylamine 16. OTHER INFORMATION	SARA 313 reportable 0.79% SARA 313 reportable 0.2% ON HMIS III 2	2