

SAFETY DATA SHEET

1. Identification of the Substance and Company

VERIFY[™] Chemical Monitoring Strip for Resert[™] Solutions

 Product No. PCC030
 NFPA 704 HAZARD RATING:

 SDS No. S282
 HEALTH: 0 FIRE: 0

 Prepared by: M. Ebers
 REACTIVITY: 0

asksteris_msds@steris.com

Date Created: March 2, 2009 Date Revised: February 28, 2013 Date Reviewed: NA

STERIS Corporation, P.O. Box 147, St. Louis, Mo 63166, US

Emergency Telephone No. 1-314-535-1395 (STERIS); 1-800-424-9300 (CHEMTREC)

Telephone Number for information: 1-800-548-4873 (Customer Service – Healthcare Products)

Albert Browne Limited, Chancery House, 190 Waterside Road, Hamilton Industrial Park,

Leicester, LE5 1QZ, UK

Emergency Phone No: +44 (0) 1895 622 639

Product/Technical Information Phone No: +44 (0) 116 276 8636

PRODUCT NAME:	PRODUCT NUMBER:
VERIFY [™] Chemical Monitoring Strip for Resert [™] Solutions	PCC030
SHIPPING INFORMATION:	NOT RESTRICTED

These products are NOT hazardous products according to the OSHA Hazard Communication Standard, 29 CFR 1910.1200.

The VERIFY[™] Chemical Monitoring Strip for Resert[™] Solutions is free of latex and natural dry rubber products.

VERIFY[™] Chemical Monitoring Strip for Resert[™] Solutions does not contain any components derived from animal origin, does not come into contact with materials of animal origin and therefore complies with the "Note for guidance of minimizing the risk of transmitting animal spongiform encephalopathy agents via human Veterinary medicinal products (EMEA/410/01 Rev. 2-October 2003)."

In the case of accidental exposure, take the following precautionary measures:

EYES: Immediately flush eyes with plenty of water for 15 minutes. Get medical attention if irritation persists.

SKIN: Immediately wash with soap and water. Get medical attention if irritation develops.

INGESTION: Give water to drink and get medical advice.

INHALATION: Remove to fresh air. Get medical attention for any breathing difficulty.

Chemical Monitoring Strips Handling and Disposal:

Handling and Storage Precautions: Keep cap tightly closed. Store at 6°C (43°F) to 30°C (86°F) and in a dry place. Do not freeze. Protect strips from exposure to light, heat and moisture. Protect strips from exposure to oxidizing agents, strong acids/alkalis and detergents.

Waste Disposal Methods: Dispose of used/expired chemical indicators and boxes in trash receptacle in accordance with federal, state, and local regulations.