

MATERIAL SAFETY DATA SHEET

FUNCTIONAL IMPRESSION TISSUE TONER (FITT) LIQUID

1 - IDENTIFICATION

Manufacturer: Kerr Corporation
Address: 1717 West Collins Avenue
City, State, Zip: Orange, CA 92867-5422
Telephone: 1-800-KERR-123
Emergency: Chemtrec 1-800-424-9300
Date Prepared: September 2, 2005

2 - COMPOSITION INFORMATION

Hazardous Ingredients

	<u>CAS #</u>	<u>PEL</u>	<u>TLV</u>	<u>%</u>
Dibutyl Phthalate	84-74-2	5 mg/m ³	5 mg/m ³	80
Denatured Alcohol	NA	NA	NA	20

3 - PHYSICAL DATA/CHEMICAL PROPERTIES

Boiling Point: N/D
Specific Gravity (H₂O = 1): 1.15
Vapor Pressure (mm Hg): N/A
Melting Point: N/A
Vapor Density (AIR = 1): N/A
Evaporation Rate: N/D
Solubility in Water: N/D
Reactivity in Water: N/A
Appearance and Odor: Clear liquid, slight alcohol odor

4 - FIRE AND EXPLOSION HAZARD DATA

Flash Point (Method Used): 60 °F
Flammable Limits: LEL: N/D UEL: N/D
Extinguishing Media: Carbon dioxide, water, dry chemical
Special Fire Fighting Procedures: None
Unusual Fire and Explosion Hazards: None known

5 - REACTIVITY DATA

Stability: Stable
Conditions to Avoid: Heat, sparks and open flames
Incompatibility (Materials to Avoid): None known
Hazardous Decomposition Products: Oxides of Carbon
Hazardous Polymerization: Will not occur

6 - HEALTH HAZARD DATA

Routes of Entry:
Skin: Avoid inhalation of vapors. Keep fumes out of eyes to prevent possible irritation. May cause allergic reactions in some sensitive individuals.
Eyes: May cause mild irritation.
Inhalation: May cause mild irritation.
Ingestion: Get medical attention.
Carcinogenicity - NTP: No
IARC Monographs: No OSHA Regulated Carcinogen: No

7 - EMERGENCY FIRST AID PROCEDURES

Skin: Wash with soap and water.
Eyes: Flush with water for 15 minutes, including under eyelids.
Inhalation: Remove to fresh air. Get medical attention if discomfort persists.
Ingestion: Rinse mouth out with water. Call physician.

8 - PRECAUTIONS FOR SAFE HANDLING & USE

Steps to be taken in case material is released or spilled: Absorb spills and place absorbent in a suitable container.
Waste Disposal Method: Incineration or landfill. Complete combustion in air gives carbon dioxide and water.
Precautions to be taken in handling and storing: Dry storage. Keep containers closed to prevent moisture absorption and contamination.

9 - CONTROL MEASURES

Respiratory Protection (Specify Type): None required under normal conditions.
VENTILATION:
Local Exhaust: None
Mechanical (General): Should be sufficient
Protective Gloves: Protective gloves are recommended.
Eye Protection: Safety glasses
Other Protective Clothing or Equipment: N/A
Work/Hygiene Practices: Handle in accordance with good personal hygiene and safety practices. Includes avoiding unnecessary exposure to material.

10 - TRANSPORTATION INFORMATION

Regulated: DOT, IATA, IMO
Proper Shipping Name: Denatured Alcohol Solution N.O. S.
Hazard Class: 3
Identification Number: NA 1987
Packing Group: II
Label: Flammable Liquid

11 - SPECIAL INFORMATION

HMIS (Hazardous Material Identification System) Rating:
H1 F3 R0
[HMIS Index: 4 - Severe Hazard; 3 - Serious Hazard;
2 - Moderate Hazard; 1 - Slight Hazard; 0 - Minimum Hazard]